PURCHASE REQUEST

Jhrr 0577 - 7091

Department: **Office of the Governor**					
Section:			PR No. _____ Date: _____		
			SAI No. _____ Date: _____		
			ALOBS No. _____ Date: _____		

Item No.	Quantity	Units of Issue	Item Description	Estimated Unit Cost	Estimated Cost
			BK 2155		
1	1	lot	Clean Intake Manifold	5,800.00	5,800.00
2	1	lot	Clean Intercooler Assy.	3,000.00	3,000.00
3	1	lot	Replace Map Sensor Hose	2,700.00	2,700.00
4	1	lot	Replace EGR Valve	6,100.00	6,100.00
5	1	lot	Replace Oil Filter	1,500.00	1,500.00
6	1	lot	Pulldown Fuel Tank and Clean	5,950.00	5,950.00
7	1	lot	Replace Valve Cover Gasket (1-set)	7,770.00	7,770.00
8	1	lot	Diagnose Engine Low Power using MUT-LLL Scanner	6,300.00	6,300.00
9	1	pc	EGR Valve	18,900.00	18,900.00
10	1	pc	EGR Valve Gasket	500.00	500.00
11	1	pc	EGR Pipe Gasket	600.00	600.00
12	3	pcs	Exhaust Manifold EGR Pipe Gasket	350.00	1,050.00
13	1	pc	Inlet Manifold Gasket	580.00	580.00
14	1	pc	Engine Oil Filter Gasket	250.00	250.00
15	1	pc	Rocker Cover Gasket	2,800.00	2,800.00
16	4	pcs	Rocker Cover Oil Seal	1,100.00	4,400.00
17	3	pcs	Rocker Cover Gasket	4,700.00	14,100.00
18	4	pcs	Rocker Cover Oil Seal	900.00	3,600.00
19	1	pc	Cylinder Head Seal	1,750.00	1,750.00
20	1	pc	Fuel Filter (Cartridge)	7,800.00	7,800.00
			Total >>>>>>>>>>>>>>>>>>>>>>> P		**95,450.00**

Purpose:

to be used for the government service vehicle under the Office of the Govenor.

	Requested by:	Cash Availability	Approved by:
			ATTY. ARTHUR C. YAP Governor
Signature:			By Authority of the Governor:
Printed Name	**GISELLE F. QUIMPO**	**EUSTAQUIO A. SOCORIN**	**ATTY. KATHYRIN FE. D. PIOQUINTO**
Designation	Chief of Staff	Provincial Treasurer	Provincial Administrator

Date of Delivery: 15 days after PO
Place of Delivery: GO
Mode of Procurement: Bidding/ Alternative Mode