

	- Bleeding of Injection Pump, Replaced Damaged Hose Clip of Pump Hose.				
16.	Labor and Materials	1	lot	6,900.00	6,900.00
	- Repair and Fabricate Damaged Parts/Lost Parts of Front Fender Flare Assy. (Left & Right) to Steel Plate including Heating.				
17.	Labor and Materials	1	lot	8,800.00	8,800.00
	- Repair and Realignment of Damage Rear Bumper Assy. Fabricate Bumper Holder (Inner) & Brackets to Angle Bars & Square Bars. Pre Heat of Damage/Broken Plastic Bumper Cover of Rear Bumper Assy.				
18.	Labor and Materials	1	lot	64,900.00	64,900.00
	- General Body Repainting - Bend out of all dents, scrape all Damage paints (portion only) including under chassis Rubberized/ Imported (urethane paint)				
	X-X				
TOTAL - - -					146,846.00

Time of Delivery : Upon receipt of P.O.
Place of Delivery : Vice Governor's Office

Purpose: For the Repair and Maintenance, Oil and Repainting of service vehicle assigned at the Vice Governor's Office - Mitsubishi Strada with Plate No. SKY 326

Requested by:		Cash Availability	Approved:
Signature:			
Printed Name:	DIOVILE A. MAR	EUSTAQUIO A. SOCORIN	DIONISIO VICTOR A. BALITE, Ph.D.
Designation:	Board Secretary II	Provincial Treasurer	Acting Vice Governor
Date:			

PROVINCIAL BUDGET OFFICE
PROVINCE OF BOHOL

CONTROL NO. 937 REC'D BY. [Signature] DATE: 7/6/20
EARMARK NO. 1021 VALID UNTIL: 12-31-20
EXPENSE CODE 7019-016 AMOUNT 146,846.00
FOR SOURCE HR CONTROLLER [Signature] DATE: 7/6/20

PETER ROSSMIR TUTALIPA
BM O