

6/15/21

APPENDIX

47

PURCHASE REQUEST
Province of Bohol

07-657-00-8000-01
899914-50213057
phpr625-2ax

Department: Office of the Provincial Agriculturist	PR No. _____	Date <u>June 8, 2021</u>
Division: RASS Division	SAI No. _____	Date: _____
Section:	OB R No. _____	Date: _____

Item No.	Quantity	Unit of Issue	Item Description	Estimated Unit Cost	Estimated Total Cost
			Combine Rice Harvester Repair & Maintenance		
1.	1	Pc.	Truck Pad Adjuster Assembly DC60 Combine Harvester Kubota (right pad)	₱ 23,181.00	₱ 23,181.00
2.	2	Pcs.	Truck Pad Adjuster Assembly DC60 Combine Harvester Kubota (left pad)	23,103.00	46,206.00
3.	1	Pc.	Truck Pad Adjuster Assembly DC70 Combine Harvester Kubota (right pad)	22,171.00	22,171.00
4.	1	Pc.	Truck Pad Adjuster Assembly DC70 Combine Harvester Kubota (left pad)	22,981.00	22,981.00
5.	4	Pcs.	Thresher Belt DC60 Combine Harvester Kubota	5,143.00	20,572.00
6.	3	Pcs.	Harvester Belt DC60 Combine Harvester Kubota	3,843.00	11,529.00
7.	3	Pcs.	Thresher Belt DC70 Combine Harvester Kubota	5,980.00	17,940.00
8.	3	Pcs.	Harvester Belt DC70 Combine Harvester Kubota	8,900.00	26,700.00
			x-x-x-x-x		
			TOTAL		₱ 191,280.00

Purpose: Spare parts/Repair and maintenance of Combine Rice harvester in support for farm mechanization program.

Time Delivery: 60 working days upon receipt of the NTP/PO

Place of Delivery: BOATech Center, Gabi, Ubay

Mode: Public Bidding

BY AUTHORITY OF THE GOVERNOR

Requested by: <i>[Signature]</i> LARRY M. PAMUGAS, Ph.D. Asst. Provincial Agriculturist 06/11/2021	Cash Availability: <i>[Signature]</i> EUSTAQUIO A. SOCORIN Provincial Treasurer	Approved by: <i>[Signature]</i> ATTY. KATHYRIN FE D. PIQUINTE PROVINCIAL ADMINISTRATOR ATTY. ARTHUR C. YAP Governor
--	--	---

2021-0462
2021-026
191,280

4

6/15/21

1517

899914/50213057-191,280

2020-0407

RESOURCES

PTO	Release check					
-----	---------------	--	--	--	--	--