

STOCK NO.	UNIT	ITEM DESCRIPTION	QTY.	UNIT COST	TOTAL COST
1	set	Horn 12 volts	1	1960.00	1,960.00
2	pc.	Relay 12 volts	1	360.00	360.00
3	pc.	socket	1	120.00	120.00
4	mt.	wire # 16	50	9.00	450.00
5	pcs.	Car freshener	5	380.00	1,900.00
6	pc.	Rotor Disc. Assy.	1	7960.00	7,960.00
7	pcs.	tubeless tire 245/70 R 16	4	13690.00	54,760.00
8	Ltrs	Engine Oil	7	480.00	3,360.00
9	pc.	Oil Filter	1	1,030.00	1,030.00
10	pc.	Fuel Filter	1	960.00	960.00
11	pc.	Tail light Assy.	1	6,200.00	6,200.00
12	pc.	Head lamp Assy.	1	13,030.00	13,030.00
13	pcs.	Head Light Bulb	2	760.000	1,520.00
14	pcs.	Stab Lar Bushing	2	690.00	1,380.00
15	pcs.	Leaf Spring Bushing	8	630.00	5,040.00
16	bot.	Penetrating Oil	1	680.00	680.00
17	pcs.	Tie Rod End	2	3,990.00	7,980.00
18	pcs.	Ball Joint Upper	2	3,870.00	7,740.00
19	pcs.	Ball joint lower	2	4,360.00	8,720.00
20	pcs.	Stud bolt w/ nut	2	590.00	1,180.00
21	set	Brake pad	1	6,760.00	6,760.00
22	bot.	Brake cleaner	1	860.00	860.00
23	pcs.	Leaf Spring	4	5,630.00	22,520.00
24	pcs.	Shock Absorber (rear)	2	8,700.00	17,400.00
25	pc.	Center Bearing Assy.	1	3,830.00	3,830.00
26	pc.	Transmission Support	1	2,730.00	2,730.00
27	pc.	Hub Bolt	1	490.00	490.00
28	pcs.	Cable tie	5	35.00	175.00
29	lot	pull /out install shock absorber (rear)	2	2,460.00	4,920.00
30	lot	Fabricate shock absorber bushing	2	3,800.00	7,600.00
31	lot	Replace Transmission support	1	1,960.00	1,960.00
32	lot	Replace Stud Bolt	2	980.00	1,960.00
33	pc.	Storage battery 12 V 11 plates	1	15,200.00	15,200.00
34	lot	Replace Center Bearing Assy.	1	1,930.00	1,930.00
35	lot	Replace stud Bolt bushing	1	1,930.00	1,930.00
36	lot	Replace Leaf spring assy.	1	7,940.00	7,940.00
		Leaf spring bushing macining			
		cutting/arinding and adjust bolt			
37	lot	Replace Tail light assy., head lamp assy.	1	4,860.00	4,860.00
		bulb and trouble shoot wiring socket			
38	lot	Tinting	1	11,500.00	11,500.00
39	lot	Compatirized wheel alignment	1	2,500.00	2,500.00
40	lot	Replace tie rod end	2	1,110.00	2,220.00
41	lot	Replace ball joint upper/lower	4	1,110.00	4,440.00
42	lot	Replace brake pad / rotor disc assy	1	2,300.00	2,300.00
		Cleaning			
43	lot	Check up/cleaning/adjust rear brake	1	1,300.00	1,300.00
44	lot	Labor change oil	1		1,800.00
		Replace oil, fuel filter, cleaning cabin and air			