

**BOHOL PROVINCIAL GOVERNMENT**  
Province of Bohol

Department: **Bohol Environment Management Office**  
Unit: **ADMINISTRATIVE**

PR No: \_\_\_\_\_ Date: **Sept. 16, 2020**  
SA No.: \_\_\_\_\_ Date: \_\_\_\_\_  
ALOBS No: \_\_\_\_\_ Date: \_\_\_\_\_

Item No.	Item Description	Quantity	Unit	Unit Cost	Total Cost
	Replace LH/RH Axle Bearing and machining Press In-Out				4,000.00
	Replace Axle Oil Seal Inner/Outer				1,800.00
	Replace Differential Bearing				900.00
	EVAPORATOR	1			7,000.00
	AIRCON BLOWER	1	pc.	5,920.00	5,920.00
	DRIER	1	pc.	1,360.00	1,360.00
	O-RING	10	pcs.	250.00	2,500.00
	EXPANSION VALVE				2,560.00
	THERMESTOR				1,040.00
	COMPRESSOR OIL				800.00
	FREON				1,800.00
	BOLT/NUT/ WASHER				1,500.00
	AXLE BEARING	2	pcs.	3,000.00	6,000.00
	AXLE OIL SEAL INNER	2	pcs.	1,100.00	2,200.00
	AXLE OIL SEAL OUTER	2	pcs.	1,100.00	2,200.00
	DIFFERENTIAL BEARING	3	pcs.	1,000.00	3,000.00
	GEAR OIL SEA 140)	3	ltrs.	280.00	840.00
	THREE BOND	2	pcs.	350.00	700.00
	Place of Delivery:	<b>BEMO</b>			
	Time of Delivery	Two months after receipt of P.O			46,120
	Mode of Procurement	<b>ALTERNATIVE PUBLIC BIDDING</b>		sub total	126,820
<b>Purpose:</b>	<b>For body repair of damage part of vehicle plate number SJC 452 (Izusu Crosswind)</b>				
Recommended by:	Ok as to availability of funds:	Approved by:			
		<b>ATTY. ARTHUR C. YAP</b>			
		GOVERNOR			
		By Authority of the Governor:			
Printed Name:	<b>JOVENCIA B. GANUB</b>	<b>EUSTAQUIO A. SOCORIN</b>	<b>ATTY. KATHYRN FE D. PIOQUINTO</b>		
Designation:	Head, BEMO	Provincial Treasurer	Provincial Administrative Officer		